



VEHICLE - WARRANTY BULLETIN

Can-Am On-Road

APRIL 24, 2025

BULLETIN 2025-3 | REVISION A

CAMPAIGN N° 2025-0003

CAUTION

All involved customers must be notified, all involved units must be corrected as per instruction herein.

Frame RH Lateral Support Screw Replacement

IMPORTANT

When receiving a vehicle for service:

- Always lookup the vehicle identification number (VIN) on the Knowledge Center to check for pending campaigns or alerts.
- Always connect the vehicle to the BRP diagnostic software (BUDS) to ensure all required updates are performed.

APPLICABILITY

MODEL YEAR	MODEL	ADMISSIBLE UNITS
2025	All Spyder F3	Go to BOSSWeb/Warranty/Campaign Monitoring to know the quantity of units in your inventory impacted by this campaign.

PROBLEM

The screw of the RH upper lateral support may not been tightened to the proper torque.

SOLUTION

Replace the right upper lateral support screw and tighten to specification.


REQUIRED PARTS

Order the parts through the regular channel.

DESCRIPTION	PART NUMBER	QTY
M10 x 55 Socket Head Screw	205505560	1



1. Remove and replace the RH upper lateral support screw.



CLAIM DETAILS

WITH WARRANTY ON DEMAND

Submit a warranty claim using the following information.

For claiming procedure, refer to the online *Dealer/Distributor Warranty Guide*.

WITH BOSSWEB

*Action	
Inspect	Repair
<input type="checkbox"/>	<input checked="" type="checkbox"/>