

SERVICE BULLETIN 631 – SPEED TWIN 900: RE-ROUTE IGNITION SWITCH HARNESS

Subject: Re-route Ignition Switch Harness			
Bulletin Number	Models Affected	VIN Range	Markets Affected
631	Speed Twin 900	From CC4121 to CG4412	All Markets

Dealers are requested to reroute the right hand switch housing and throttle position sensor harnesses as described in the procedure outlined in **Service Bulletin 631**, found in the Technical Information section of [TriumphOnline.net](https://www.triumphonline.net).

Service Bulletin 631

 SB631.pdf

Reminder: use the "[VIN Enquiry](#)." function within TOL to search for any outstanding bulletins or recalls whenever a new bike arrives, during PDI, or when a Triumph owner visits your dealership.

Note:

- Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory.
- Unmodified motorcycles can be identified by checking the 'VIN Enquiry' on www.triumphonline.net.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.