

SPEED TWIN 900 – FRONT FORK NOISE

Triumph has identified a noise that may be heard in the MY25 Speed Twin 900 left-hand fork under compression especially when the fork is cold (at room temperature).

This noise is caused by the hydraulic behavior of the fork.

There are **no safety concerns or loss of performance associated with this noise**. Therefore, it is not necessary to replace any components.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.