

CONDENSATION ON INSTRUMENT PACKS AND HEADLAMPS

Triumph is aware of some customer complaints relating to condensation in the instrument pack and headlamp on various models, as seen in the examples below.

Example instrument pack:



Example headlamp:



Condensation is normal and expected with electrical components of this type. As they generate heat during use, ventilation is necessary for cooling and airflow. This allows moisture in the air to enter and condense on surfaces, especially in cool or damp conditions.

Condensation typically clears within about 15 minutes as the component warms up and the air circulates, but the time taken will vary depending on the component and conditions and could be longer.

This condensation is **not** indicative of a defect and does not require repair. **Warranty claims for condensation of this type will be rejected.** Should any customer report this as a concern, please

inform them of the above and that no repairs are required.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.