

WSD5 Workshop campaign - Check coolant reservoir cap and replace if necessary

WSD5 Workshop campaign - Check coolant reservoir cap and replace if necessary

ID Number	WSD5
Model(s)	911 (992)
Model Year(s)	2024 - 2026
VIN List	Attached
Number of Affected VINs	820
Issue Description	A cap on the coolant expansion tank with incorrect pressure compensation valve was potentially installed on the affected vehicles. If this is the case, coolant loss cannot be ruled out with an increase in pressure in the cooling system. For this reason, the coolant expansion tank cap must be checked and replaced if necessary.
What Porsche Centers Should Do	Please arrange for this action to be carried out on the affected vehicles during the next workshop visit or before the vehicles are handed over to customers. (Repair available a of 04/21/2025)
TI	WSD5
Part Status	Status 2

Required parts - only if needed

No parts are required for checking the cap on the coolant expansion tank.

Please order the cap for the coolant expansion tank only if necessary.

Send a parts PRMS ticket with pictures attached to order part - see Technical Information

Warranty processing

Validity:

This workshop campaign will be carried out up to 01.05.2030 and will be closed by the specified date.

Please note that warranty claims can only be processed up to this date.

Scope 1: Coolant expansion tank cap

WSD5 Workshop campaign - Check coolant reservoir cap and replace if necessary

Damage Code	WSD5 66 000
Repair Code	1
Labor time	11 TU

Scope 2: Checking and replacing coolant expansion tank cover

Damage Code	WSD5 66 000
Repair Code	2
Labor time	11 TU

Please enter the campaign carried out in the Warranty and Maintenance logbook for the vehicle.

Attachments

1. [WSD5 Workshop Campaign VIN List 04.21.2025 V2 HT.xlsx](#)