

2024 Plateau

2-DOOR NEXT TO FRIDGE WON'T LOCK KEEP COMING OUT. LATCH INTERNAL MECHANISM FAILED. NEED TO REMOVE AND REPLACE WHISPER LATCH

LABOR REQUESTED: .30 0.20 approved. We will send you a new latch under warranty.