

2025 Plateau

COMPLAINT: Rear bay door will not open.

CAUSE: passenger side latch will not open.

CORRECTION: removed panel on back on compartment door and was manually able to open door. Found latch sticking so I lubed latch and adjusted catch. Door opens and closes now. Then found the door to not lock had to adjust the latch to get the key to lock and unlock the latch. ob complete.

LABOR: 0.3 PARTS: POWER LUBE W/PTFE 0.30 approved.