

Technical Service Bulletin (TSB)
RSU With Additional Sleep Cycles for HV Battery Integrity Check
- Flash: Integrated Dual Charging Module (IDCM) Updates 6A1

REFERENCE:	TSB: 08-135-25 REV. A GROUP: 08 - Electrical	Date:	May 6, 2025	REVISION:	08-135-25
VEHICLES AFFECTED:	2025 (LB) Dodge Charger This bulletin applies to vehicles built on or before April 03, 2025 (MDH 0403XX) equipped with 400V G2500 FR/RR Elec Drive Motors (Sales Code ELD).			MARKET APPLICABILITY: <input checked="" type="checkbox"/> NA <input checked="" type="checkbox"/> MEA <input checked="" type="checkbox"/> SA <input checked="" type="checkbox"/> IAP <input checked="" type="checkbox"/> EE <input checked="" type="checkbox"/> CH	
CUSTOMER SYMPTOM:	NOTE: **This service action is being canceled, it is not applicable to the 2025 (LB) Dodge Charger.**				
CAUSE:	IDCM software update				

This bulletin supersedes Technical Service Bulletin (TSB) 08-135-25, date of issue April 29, 2025, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include converting this TSB to an information only TSB, updating the Customer Symptoms to a note, adding a Discussion section with a new note and updating the Policy section.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 25-082, date of issue April 29, 2025. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

NOTE: The RSU portion of this service bulletin covers U.S. and Canada only.

****DISCUSSION:**

NOTE: This service action is being canceled, it is not applicable to the 2025 (LB) Dodge Charger.

POLICY:

Information Only.**