

**Technical Service Bulletin (TSB)**  
**Global Telematics Box Module (TBM)**  
**Firmware Over The Air (FOTA) Update**

<b>REFERENCE:</b>	<b>TSB:</b> 08-155-25 <b>GROUP:</b> 08 - Electrical	<b>Date:</b>	May 10, 2025	<b>REVISION:</b>	—
<b>VEHICLES AFFECTED:</b>	<b>2023 - 2025 (JL) Jeep Wrangler</b> <b>2023 - 2025 (JT) Jeep Gladiator</b> This bulletin applies to vehicles built on or before <b>May 05, 2025 (MDH 0505XX)</b> equipped with Global Telematics Box Module (TBM) (Sales Code RDG).			<b>MARKET APPLICABILITY:</b>	
				<input checked="" type="checkbox"/> NA	<input type="checkbox"/> MEA
				<input type="checkbox"/> SA	<input type="checkbox"/> IAP
				<input type="checkbox"/> EE	<input type="checkbox"/> CH
<b>CUSTOMER SYMPTOM:</b>	<b>The following software enhancement is available:</b> <ul style="list-style-type: none"> <li>This software update enables the feature Active Cabin Ventilation (ACV).</li> </ul>				
<b>CAUSE:</b>	Software update				

**REPAIR SUMMARY:**


This bulletin provides information regarding the latest Firmware Over The Air (FOTA) update and provides the service technician an overview of the steps a customer will need to take to complete the update. The TBM software will be updated from 5.15, 5.41 or 5.43 to 5.53 software level.

**NOTE: National launch for this FOTA update is expected to begin: April 14, 2025.**

**DISCUSSION:**

Vehicles sold in the U.S. and Canada can now receive software updates “over-the-air”. Updates to software will occur in a phased roll-out. The software is updated through a built in cellular modem in the vehicle. Customers will see a notification on their radio screen when new software is available for their radio [Fig. 1](#). The owner will have the option to update the radio or schedule the update for later. There is not an option to decline the update indefinitely, the update must be performed.

**NOTE: This is an Information Only Technical Service Bulletin to inform the dealer how the FOTA update is performed. This document does not contain a LOP for reimbursement.**




**Fig. 1**  
Software Acceptance Screen

1. The vehicle needs to be in 'Park'. The ignition needs to be in the off position.
2. If the customer selects "Update Now" Fig. 1 they can shut off the vehicle and leave. The update will be completed automatically.

**NOTE: This step may take several minutes to complete.**

3. Upon completion of update, the radio will display a confirmation message Fig. 2.



**Fig. 2**  
Software Update Confirmation Screen

## **POLICY:**

Information Only.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*