



STAR ONLINE PUBLICATION



Case Number: S2523000020

Release Date: May 2025

Symptom/Vehicle Issue: Diagnostic Trouble Code (DTC) U300A-29

Customer Complaint/Technician Observation: When Ignition is changed from RUN to Start, smart lamp module left/right (SLML / SLMR) sets DTC U300A-29 (Ignition Switch - Signal Invalid).

Discussion: If U300A-29 is set, please clear the DTCs on SLML and SLMR. Then restart the truck and check for DTCs.

Did the DTC U300A-29 return active 10 seconds after the engine is started?

>>>Yes>>> The code has returned in active state. Follow published standard diagnostics in Service Library.

>>>No>>> The DTC is not active. If the DTC reappears as stored, do not repair or replace the headlamp. Engineering is aware and investigating the concern. The headlamps will work as designed with no issue. A future service publication will address a repair.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.