

ONP D006 – TWIN SPEED TRANSFER CASE HYDRAULIC PUMP

OWNER NOTIFIED PROGRAM D006 – TWIN SPEED TRANSFER CASE HYDRAULIC PUMP	
AFFECTED MODELS	22-25MY Range Rover 23-25MY Range Rover Sport 21-25MY Defender and Discovery
VOLUME AFFECTED	22 US 6 CAN
REPAIR	A potential concern has been identified on certain vehicles, where the transfer case clutch and / or All Wheel Drive (AWD) lock cannot perform as designed. This may show as a reduction in torque to the front axle during driving or as an inability to apply the AWD lock. A replacement of the transfer case control module (TCCM) and hydraulic pump is required.
REPAIR TIME	Up to 6.2 hr. + DIDO
CAMPAIGN LAUNCH	May 6th, 2025
NOTES	Affected unsold vehicles should have the repair completed prior to customer handover. Sold vehicles must have the repair completed at the next earliest opportunity. Please confirm affected VINs using the warranty portal. This is a connected campaign where affected vehicles are identified through Over-the-Air vehicle data. Additional VINs are expected to be added as more are identified.