

## SERVICE ACTION D012 – CAR CONFIGURATION FILE

SERVICE ACTION D012 – CAR CONFIGURATION FILE	
AFFECTED MODELS	25MY Range Rover
VOLUME AFFECTED	2382 US 186 CAN
REPAIR	Certain Range Rover vehicles imported into North America, Canada and Mexico are unable to achieve the maximum speed stated. An update to the car configuration file (CCF) is required.
REPAIR TIME	Up to 0.3 hr. + DIDO
CAMPAIGN LAUNCH	May 6th, 2025
NOTES	Affected unsold vehicles should have the repair completed prior to customer handover. Sold vehicles must have the repair completed at the next earliest opportunity. Please confirm affected VINs using the warranty portal.