

UPDATE PRIOR TO SALE H537 – JUNCTION BOX REPAIR

UPDATE PRIOR TO SALE H537 – JUNCTION BOX REPAIR	
AFFECTED MODELS	23-24MY F-TYPE
VOLUME AFFECTED	602 US 108 CAN
REPAIR	On certain vehicles, the Electric Power Assisted Steering (EPAS) wiring harness junction box may become corroded over time. A mylar based insulator patch is needed.
REPAIR TIME	0.4 hr. + DIDO
CAMPAIGN LAUNCH	April 14th, 2025
NOTES	<p>Unsold retailer inventory on May 7th, 2025 - 72 US 72 CAN</p> <p>Additional vehicles will be wholesaled from ports depending upon retailer demand as part of the Jaguar Sunset program.</p> <p>Retailers are required to complete the UPS campaign prior to vehicle sale and delivery.</p>