

## DTC's P013E-00, P014A-00, P2270-00, P2272-00 STORED WITHIN THE PCM – MID CATALYST HO2S - 4.4L

### Customer Voice:

- Malfunction indicator lamp comes on.

### Technical Description:

- Currently under investigation, left and/or right mid catalyst heated oxygen sensor (HO2S) LR159844 could be at fault.

### Status:

- If one or more of these listed DTC's are present in the PCM, please replace the applicable sensor.
- Please raise an EPQR and please reference SSM76306 with all the relevant information.
- Do not discard the removed part(s), it will be required for parts return request which will be arranged by relevant JLR engineering team.

Refer to SSM 76306

### Range Rover

- 22-23MY Range Rover
- 23MY Range Rover Sport

