

## ENGINE OIL COOLER PIPE LEAK – 4.4L NC11

### Customer Voice:

- Oil leak under engine area

### Technical Description:

- Engine oil cooler feed and/or return pipe leaking engine oil from the oil pan extension oil cooler port(s).
- Pinched, split or deformed O-ring.

### Status:

- Confirm oil leak is at the engine cooler line at the oil pan extension.
- Take clear photographs to attach to EPQR of:
  - Two oil cooler bores in the oil pan
  - Affected O-rings for any damage (do not remove them from pipe).
  - Picture of the serial number label of pipe (see lower picture)
  - Once repairs are complete, please attach all documentation to an EPQR and reference SSM76308.
- Please keep all parts for Parts return request.

SSM 76308

### Range Rover

- 24-25MY Range Rover
- 24-25MY RR Sport

### Defender

- 25MY Defender

