



Bulletin No.: PIT6281B

Published date: 05/5/2025

Preliminary Information

PIT6281B SES MIL With ECM DTC P00FF and BCM DTC U1962

Models

| Brand: | Model: | Model Years: | VIN: | | Engine: | Transmissions: |
|-----------|--------------|--------------|------|-----------------|---------|----------------|
| | | | from | to | | |
| Cadillac | Escalade | 2025 | SOP | January 8, 2025 | All | All |
| Cadillac | Escalade ESV | 2025 | SOP | January 8, 2025 | All | All |
| Chevrolet | Suburban | 2025 | SOP | January 8, 2025 | All | All |
| Chevrolet | Tahoe | 2025 | SOP | January 8, 2025 | All | All |
| GMC | Yukon | 2025 | SOP | January 8, 2025 | All | All |
| GMC | Yukon XL | 2025 | SOP | January 8, 2025 | All | All |

| | |
|-----------------------------------|--|
| Involved Region or Country | North America |
| Condition | A customer may experience a SES MIL and when scanning for DTCs there may be an ECM P00FF and BCM U1962 set. |
| Cause | The cause of this condition could be the BCM calibrations. |

Correction:

Updated BCM calibrations have been released. Using TLC/SPS reprogram the BCM with the latest calibrations.

NOTE: Do not replace the Telematics Control Module or Body Control Module.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.


| Labor Operation | Description | Labor Time |
|-----------------|---|---------------------------|
| 2810215 | Body Control Module Reprogramming with SPS | Use Published Time |

Additional SI Keywords

U0499 U0485

Version History

| | |
|-----------------|--|
| Version | 3 |
| Modified | 11/12/2024 - Created on. 01/09/2025 - Updated Models 05/05/2025 - Update to the Cause, Correction, Models, and Warranty sections. |

 GM Global Brands

© 2025 General Motors. All Rights Reserved.