



Bulletin No.: PIP6054
Published date: 05/7/2025

Preliminary Information

PIP6054 2023 Corvette Intermittent no drive or reverse

Models

Brand: Chevrolet **Model:** Corvette **Model Years:** 2023 **VIN:** from All to All **Engine:** All **Transmissions:** All

Involved Region or Country	North America
Condition	Some customers may comment on an intermittent no drive or no reverse complaint. Could be just no drive engagement or no reverse engagement. If this condition is present there will be no DIC messages, no diagnostic trouble codes and often a shut down and restart will return normal transmission operation.
Cause	Software anomaly in the TCM software.

Correction:

New software was released to correct this condition on or around 3/25/2025. Reprogram the TCM with the latest software.

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
* 8480698	Technician road test for verification of concern and update programming of the TCM.	.5 Hrs
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	05/07/2025 - Created on.