



**Bulletin No.:** PIP6063

**Published date:** 05/8/2025

## Preliminary Information

### PIP6063 Diagnostic Aid 1.3 L3T Leaking Turbocharger Oil Return Pipe Gasket

#### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN:</b> from to	<b>Engine:</b>	<b>Transmissions:</b>
Buick	Encore GX 2025		All	All 1.3 L3T	All
Chevrolet	Trailblazer 2025		All	All 1.3 L3T	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Condition</b>	<b>Engine oil leak at turbocharger oil return pipe gasket area.</b>
<b>Cause</b>	<b>Turbocharger oil return pipe gasket damaged.</b>

#### Correction:

If an engine oil leak is being diagnosed and it is in the area of the turbocharger return oil pipe gasket, clean off the area and verify the leak is coming from the gasket sealing area.

Remove and inspect the gasket for any signs that it may not be making full contact with the sealing surfaces or any damage to the gasket.

Replace the turbocharger oil pipe return gasket.


See pictures below for gasket location and types of damage to inspect for.





**Version History**

<b>Version</b>	<b>1</b>
<b>Modified</b>	PIP6063 Created on 5/8/2025

 GM Global Brands  
© 2025 General Motors. All Rights Reserved.