



STAR ONLINE PUBLICATION



Case Number: S2508000003 Rev. A

Release Date: May 2025

Symptom/Vehicle Issue: Speed Sensing Door Locks do Not Operate or Other Customer Programmable Features

Discussion: The speed sensing auto door lock feature is not locking the doors upon driving as expected. Use the scan tool to access the Instrument Panel Cluster (IPC), select the MISC folder, select IPC Customer Programmable Features, select speed lock door enable or other feature as needed to re-enable.

Note: Trucks with cluster sales code JAN do not have the below options.

1C6RRFFG7SN565900


IPC

Instrument Panel Cluster


Flash DTCs Data Misc Functions System Tests Actuators Details Configuration

NAME

IPC Customer Programable Features

 IPC Customer Programable Features

Please select which programable features you would like to change below.

 Once complete with programable features select Done from the drop down menu.

Selected: Speed Unit ▾

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Center Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.