



SIB 12 06 25

2025-05-22

## SERVICE ACTION: CHECK HIGH PRESSURE PUMP ELECTRICAL CONNECTOR

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

<input type="checkbox"/>	THIS REPAIR IS MOBILE FRIENDLY
<input type="checkbox"/>	THIS REPAIR IS REMOTE SOFTWARE UPGRADE (RSU) FRIENDLY

### MODEL

G70 (7 Series Sedan)
----------------------


### AFFECTED VEHICLES

- Vehicles which require this campaign to be completed will show it as "Open" when checked either in AIR, AWP, Campaign Summary, or Warranty Vehicle Inquiry
- Please make sure you check your center's inventory as soon as possible. You can see a list of affected vehicles in Inventory Campaign Details (ICD) under ROSS.
- For centers that qualify, this Service Action's repair is eligible to be performed via Mobile Assistance

### SITUATION

The electrical connector for the bank 1 high pressure pump may not have been locked correctly.

### PROCEDURE



1. Remove the acoustic cover as described in Repair Instruction 11 12 070 "Removing and installing/replacing the acoustic cover".

2. Check and if necessary, lock the electrical connector on the bank 1 high pressure pump (1).

3. Reassemble the vehicle.

### CLAIM INFORMATION

Reimbursement for this Service Action will be via normal claim entry utilizing the applicable work package information below.

-

<b>Repair Code:</b>	<b>0012460600</b>	<b>G70 S68T Checking lock of high-pressure pump connector and relocking if necessary</b>
---------------------	-------------------	--

Below are the special flat rate labor operation code choices for this action.

**Completion before the first vehicle delivery to a customer (New in-stock/No in-service date), or the vehicle is already in the workshop for another reason and/or repair.**

Work Pkg	Labor Operation	Description (Plusposition)	Labor Allowance
# 1	00 78 665	Checking the high-pressure pump connector on cylinder bank 1 and, if necessary, locking it in place again.	3 FRU
Or:			
# 2	00 78 666	Vehicle was already taken care of through another repair	1 FRU

Or:

The vehicle arrives at your center and this Service Action shows open (No other Main work will be performed or claimed during this workshop visit).

Work Pkg	Labor Operation	Description (Main work)	Labor Allowance
# 3	00 78 135	Checking the high-pressure pump connector on cylinder bank 1 and, if necessary, locking it in place again.	5 FRU
Or:			
# 4	00 78 136	Vehicle was already taken care of through another repair	1 FRU

Only one of the flat rate labor operation codes listed above can be used for claim submission and reimbursement. Also, only one Main work flat rate labor operation code can be claimed per workshop visit.

Claim Repair Comments

Reference the SIB number, the issue (briefly), and the work package (WP) number performed in the technician’s RO notes, and in the claim comments (For example: B12 06 25 HP Fuel Pump Connector WP 1), unless otherwise required by State law.

FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topic of this bulletin: Submit your feedback in the rating box at the top of this bulletin
Warranty Feedback	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS ticket to the Warranty Department, or use the chat available in the Warranty Documentation Portal
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS ticket to the Parts Department

