



STAR ONLINE PUBLICATION



Case Number: S2505000002 Rev. A


Release Date: May 2025

Symptom/Vehicle Issue: Antilock Brake System (ABS) Light On. Diagnostic Trouble Code (DTC) C0044-01 Set.

Discussion: Follow the published diagnostics for C0044-01-BRAKE PRESSURE SENSOR 1 - GENERAL ELECTRICAL FAILURE. If testing leads to replacement of a component, it is necessary to replace the entire brake unit. The integrated control unit (ICU) is comprised of the ABS module and the hydraulic control unit (HCU).

005 - Brakes / 500 - Hydraulic Control Unit, Brake Tubes and Hoses / 505 - Hydraulic Control Unit / EBB HCU, Anti-Lock Brakes

[View Mapping](#) [Shopping Cart](#)



Integrated Control Unit (parts 1 and 3).

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.