



# Service Bulletin

Bulletin No.: PIP6066A

Date: May, 2025

## PRELIMINARY INFORMATION

**Subject: 6.6L L5P Setting DTC P060C**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 2500	2024-2025		All	All	6.6 L5P	All
Chevrolet	Silverado 3500	2024-2025		All	All	6.6 L5P	All
GMC	Sierra 2500	2024-2025		All	All	6.6 L5P	All
GMC	Sierra 3500	2024-2025		All	All	6.6 L5P	All

<b>Involved Region or Country</b>	North America. Israel, Palestine, Middle East
<b>Condition</b>	A customer may complain of a Malfunction Indicator Light (MIL).
<b>Cause</b>	This may be caused by a software anomaly.

### Correction

If P060C is set in the ECM, please use the scan tool to check the DATA DISPLAY > ECU DATA > PROCESSER SECURITY FAULT REASON CURRENT. If the reason is Vehicle fails to decelerate as indicated by Actual Axle Torque, Engineering is currently working on a design improvement.

Please clear the DTC and return the vehicle to the customer.

The PI will be updated or replaced with TSB once a determination has been made.

<b>Version</b>	2
<b>Modified</b>	05/16/2025 - Created on. 05/23/2025 - updated to add 2024 model year

