

9100592

05/28/2025

MY 20-25 DD, 19-26 DT, 20-24 DF, 19-26
DJ, 22-25 DP, 20-26 D2

GPOP - Issue Review System

Part Number: 68291948A\$, 68675164A\$

Part Description: LAMP Courtesy/Ambient

Issue Description: Lightguide not fully seated into the retainer during IP sub-assembly due to inconsistent operator installation effort, leading to latent BSR issue that manifests under customer usage conditions. Solution:
remove and reinstall lightguide to be fully seated in the bracket retainer.