



Service Bulletin

Bulletin No.: PIT6391

Date: May, 2025

PRELIMINARY INFORMATION

Subject: Charging Animation Inoperative On One Lamp

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	VISTIQ	2026		SORP	VIN # TZ700828	ALL	ALL

Involved Region or Country	North America
Condition	A customer may notice that charging animation does not function on either the headlamps or the tail lamps. After replacing a headlamp or tail lamp for a repair a tech may notice that charging animation only works on one headlamp or tail lamp.
Cause	MLD software anomaly

Correction

If charging animation is not working on both headlamps- replace both headlamps.

If charging animation is not working on both tail lamps- replace both tail lamps.

If a single headlamp or tail lamp is being replaced due to an unrelated repair and the vehicle was built before the breakpoint, replace both the LH and RH lamps as a pair.

Version	1
Modified	05/23/2025- Created on.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2025 General Motors. All Rights Reserved.