



# VOLKSWAGEN DEALER COMMUNICATION

## Repair Available – Emissions Service Action 26OB / Exhaust Pressure Sensor

**This notice is for:** All Dealer Personnel

**Date:** May 19, 2025

**About this Service Action:** In affected vehicles it is possible that a faulty exhaust pressure sensor may impact tailpipe emissions. To address this issue, the exhaust pressure sensor will be replaced on affected vehicles.

- Repair:**
- REPAIR AVAILABLE – May 20, 2025
  - See ELSA and Service References in Elsa2Go for complete repair & claiming instructions.
  - Check both the daily Campaign Open Inventory report and OMD for affected vehicles in inventory. Verify OPEN status in ELSA on the day of repair.
  - Repair every affected inventory vehicle before delivery to consumers.

**Parts Department:** See the campaign circular for parts ordering information. Please coordinate with your service department to ensure that parts are available for all scheduled appointments.

**Affected Vehicles**

Country	Beginning Model Year	Ending Model Year	Vehicle	Vehicle Count
USA	2025	2025	JETTA	19
USA	2025	2025	TAOS	9
CAN	2025	2025	JETTA	63
CAN	2025	2025	TAOS	242

*\*Counts reflect overall population; some vehicles may have already been repaired. Check Campaigns/Actions screen in Elsa on the day of repair to verify that a VIN qualifies for repair under this action. Elsa is the only valid campaign inquiry & verification source.*

- Notes:**
- Schedule owner repairs immediately
  - Owner mailing – May 2025
  - Loaner/rental coverage – see campaign circular

**-END OF MESSAGE-**

*Ensure all dealer personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Volkswagen Public Relations.*