

<b>Reference</b>	SSM76325
<b>Models</b>	New Range Rover / L460 New Range Rover Sport / L461
<b>Title</b>	Diagnostic Trouble Code (DTC) P0A1B stored in the Electric Power Inverter Converter (EPIC)
<b>Category</b>	Driveline
<b>Last modified</b>	14-May-2025 00:00:00
<b>Symptom</b>	503000 Automatic Transmission Engagement Concerns

**Content**      **Model / Model Year / Derivative**

Range Rover / 24MY onwards / PHEV only  
Range Rover Sport / 24MY onwards / PHEV only

**Situation:**

JLR Engineering investigations have identified that certain vehicles are displaying a loss of drive, indicated by a 'loss of drive' warning in red on the instrument panel cluster and the Malfunction Indicator Lamp (MIL) is illuminated. The fault occurs during start-up and only with the vehicle stationary. The Diagnostic Trouble Code (DTC) P0A1B-00 is stored in the Electric Power Inverter Converter (EPIC).

**Action:**

Refer to the Service Information below.

**Service Information:**

If DTC P0A1B-00 is stored in the Gen 4 PHEV EPIC, retailers are to complete the Electric Power Inverter Converter Health Check application through the Workflow/Diagnostic Test. The Workflow/Diagnostic Test may request you to raise a Technical Assistance (TA) to PTS\_120 if required. Engineering are currently developing a software update for this concern.

(Ref 000397576 / 4491)

anBhdHRicm7MjAyNS0wNS0xNFQxNToyNTozMy43MDdaOzE2NS4yMjUuMzguMjUyOw==