



Service Bulletin

Bulletin No.: PIE0827

Date: April, 2025

ENGINEERING INFORMATION

Subject: Engineering Information - Information on Headlamp, Turn Signal and/or Daytime Running Lamps Flickering and/or Inoperative

Attention: Proceed with this EI ONLY if the customer has commented about this concern AND the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the EI does not show in GWM/IVH, disregard the PIE, and proceed with diagnostics found in published service information. THIS IS NOT A RECALL refer to Service Bulletin 04-00-89-053 for more details on the use of Engineering Information bulletins.

Brand:	Model:	Model Year:		Breakpoint:		Engine:	Transmission:
		from	to	from	to		
GMC	Sierra EV	2024	2025	—	—	—	—

Involved Region or Country	U.S. Dealers ONLY
Condition	Some customers may comment on a headlamp related concern such as (but limited to) the following issues: • Headlamp flickering and/or inoperative • Turn signal flickering and/or inoperative, shown in video above. • Daytime running lamps flickering and/or inoperative, shown in video above.
Cause	GM Engineering is attempting to determine the root cause of the above condition. Engineering has a need to gather information on vehicles PRIOR to repair that may exhibit this condition. As a result, this information will be used to "root cause" the customer's concern and develop/validate a field fix.

Correction

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Important: This Engineering Information (EI) can only be completed by certified repair facilities who have met all specific training, tool and equipment requirements pertaining to the vehicle Brand and Model serviced. Repairs must be performed by a technician who has successfully completed the required training.

If you encounter a vehicle with the above concern, take a clear picture, video of the issue, and contact the engineer listed below BEFORE further diagnosis and/or part replacement.

Contact Information

Contact Information has been redacted.

Please include the following information if leaving a message:

- Technician name
- Dealer name and phone number
- Complete VIN and repair order (R.O) number

On the repair order, document the date and time the call was placed (even if the engineer was not reached).

If engineering is unable to return the call within one hour, proceed with diagnosis and repair based on information found in SI.

Warranty Information

If an engineer was contacted or required information was provided, use:

Labor Operation	Description	Labor Time
2080788*	Engineering Information - Information on Headlamp, Turn Signal, Daytime Running Lamps Flickering/Inoperative	0.3 Hrs.
*This is a unique Labor Operation for bulletin use only.		

Version	1
Modified	Released April 10, 2025

