



# Service Bulletin

Bulletin No.: 25-NA-094

Date: April, 2025

## INFORMATION

**Subject: Information on Lane Keep Assist Unavailable after taken out of Transport Mode**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2026	2026	—	—	All	All
GMC	Terrain	2026	2026				

<b>Involved Region or Country</b>	North America, Middle East
<b>Condition</b>	Some customers may comment on a Lane Keep Assist Unavailable message on the IPC after the vehicle is taken out of Transport Mode.
<b>Cause</b>	This condition may be caused by a software anomaly.
<b>Correction</b>	After the vehicle is taken out of Transport Mode, usually at PDI, make sure it completes a sleep cycle of at least 10 minutes. Do not make any attempts to repair.

**Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.**

<b>Version</b>	1
<b>Modified</b>	Released April 14, 2025

