



SSM 53876 2020-2023 Aviator/Explorer, 2021-2023 Bronco - 10R60 Automatic Transmission - Harsh/Delayed Engagement And/Or Harsh/Delayed Shift

Some 2020-2023 Aviator/Explorer and 2021-2023 Bronco vehicles equipped with a 10R60 transmission may exhibit harsh or delayed engagement/shift concerns. Refer to Workshop Manual (WSM), Section 307-01 > Diagnosis and Testing for normal diagnostics. The WSM has been updated with information from previously published articles related to this concern.