



**Global Telematics Box Module Over The Air Update from
5.39.1 to 5.65 TBM2.0 Software Version (FOTA)**

6/10/2025

**VEHICLES
AFFECTED:** 2023 - 2025 (JL) Jeep Wrangler
2023 - 2025 (JT) Jeep Gladiator
This bulletin applies to vehicles equipped with a Global Telematics
Box Module (TBM) (Sales Code RDG)

MARKET APPLICABILITY:

- | | |
|--|------------------------------|
| <input checked="" type="checkbox"/> NA | <input type="checkbox"/> MEA |
| <input type="checkbox"/> SA | <input type="checkbox"/> IAP |
| <input type="checkbox"/> EE | <input type="checkbox"/> CH |

**CUSTOMER
SYMPTOM:** Customers may experience one or more of the following:

- Error display of "Uconnect Box Requires Service/Wifi Unavailable" pop-ups; [TBM DTC B22A9-96 Internal Performance Failure].
- Error display of "Uconnect Box Requires Service" pop-ups; [TBM DTCs B1560, B1561, B1562 - Antenna loose connection].