

Technical Service Bulletin (TSB)
Front Power Outlet Cover Missing

REFERENCE:	TSB: 08-184-25 GROUP: 08 - Electrical	Date:	June 10, 2025	REVISION:	—
VEHICLES AFFECTED:	2025 (JL) Jeep Wrangler This bulletin applies to vehicles built on or after May 02, 2025 (MDH 0502XX) and on or before May 05, 2025 (MDH 0505XX).	MARKET APPLICABILITY:			
		<input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH			
CUSTOMER SYMPTOM:	Customers may comment on the following: <ul style="list-style-type: none"> The front power outlet is missing the outlet cover. 				
CAUSE:	Incorrect front power outlet				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 25-107, date of issue June 10, 2025. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves replacing the front power outlet.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
08-28-05-90	Cap, Power Outlet; Front - Replace (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
Failure Code	ZY	Service Action	

RELATED LOP:

Labor Operation No:	Labor Description	Skill Category	Labor Time
08-28-05-60	PHEV Equipped - High Voltage Battery Power Down / Up and Loss of Isolation Test (0 - Introduction)	6 - Electrical and Body Systems	0.6 Hrs.

SPARE PARTS:

Qty	Part No.	Description	Notes
1	68718228AA	Cap, Power Outlet - Ignition Feed	

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Is the vehicle on the RSU list?
 - YES >>> Proceed to [Step 2](#).
 - NO >>> This bulletin does not apply.
2. **For PHEV vehicles only, power down the high voltage system.** Refer to the detailed procedures available in DealerCONNECT > Service Library> under: 12 - Electrified Powertrain System / High Voltage Battery / Standard Procedure.
3. Replace the front power outlet. Refer to the detailed procedures available in DealerCONNECT > Service Library> under: 08 - Electrical / 8W - Power Distribution / Outlet, Power / Removal and Installation.
4. **For PHEV vehicles only, power up the high voltage system.** Refer to the detailed procedures available in DealerCONNECT > Service Library> under: 12 - Electrified Powertrain System / High Voltage Battery / Standard Procedure.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.