



SSM 53954 2025 Bronco Sport - Badlands/Sasquatch - Clicking/Creaking/Clunking And/Or Rattle Noise From The Front Struts When Turning The Steering Wheel

Some 2025 Bronco Sport vehicles equipped with 2.0L engine with Badlands package and 2025 Bronco Sport vehicles equipped with 1.5L engine with Sasquatch package may exhibit a clicking, creaking, clunking and/or rattle noise from the front struts when turning the steering wheel. Ford is aware of the concern and this condition does not affect vehicle durability and no additional diagnosis or service is required for this condition at this time. Inform customers that they can continue to drive the vehicle and engineering is currently working on a solution for this condition that is expected by the end of the 3rd quarter of 2025. Monitor Professional Technician System (PTS) for additional information and schedule a service appointment for customers once the repair becomes available.