



## STAR ONLINE PUBLICATION



**Case Number:** S2523000058

**Release Date:** June 2025

**Symptom/Vehicle Issue:** C2206 Diagnostic Trouble Code (DTC) Set After Adding Aftermarket Mopar Vehicle Protection (MVP) Speedometer Correction Plan.

**Discussion:** Engineering is aware of concerns on vehicles equipped with sales code XMB – Central ADAS Decision Module (CADM) setting C2206 Vehicle Configuration Mismatch after adding a MPV Speedometer Correction Plan. At this time, it is not advised to perform any additional repairs. Contact MVP to remove the plan until a resolution is in place. In addition, select “Get Notified” at the top of Service Library to be notified when the resolution is available.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.**