

REFERENCE:	TSB: 23-025-25 GROUP: 23 - Body	Date:	June 18, 2025	REVISION:	—
VEHICLES AFFECTED:	2022 - 2024 (B1) Jeep Renegade This bulletin applies to vehicles built on or before August 02, 2023 (MDH 0802XX).			MARKET APPLICABILITY: <input type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> EE <input type="checkbox"/> IAP <input checked="" type="checkbox"/> SA <input type="checkbox"/> CH NOTE: This bulletin applies to South America markets.	
CUSTOMER SYMPTOM:	Customers may experience the following: <ul style="list-style-type: none"> The fuel tank cap hatch does not open. 				
CAUSE:	Defective hatch motor				

REPAIR SUMMARY:

This bulletin involves replacing the fuel tank hatch.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
14-60-17-9E	Hatch, Fuel Tank - Replace	6 - Electrical and Body Systems	0.3 Hrs.
Failure Code	ZZ	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1	51964194 - SA 68255556AA - Mopar	Fuel Filler Housing	

DIAGNOSIS:

If the customer describes a symptom/condition above, perform the Diagnostic Procedure.

REPAIR PROCEDURE:

1. Replace the fuel tank hatch. Refer to the detailed service procedures available in DealerCONNECT/ Service Library under: Service Info> 7210G82 - Portinhola/Tampa do Reservatório de Combustível - Remoção/Recolocação.

NOTE: After applying this TSB, it is not necessary to send DID-I or DID-A.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.