

GENERAL MOTORS
DCS7260
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 26, 2025

Subject: N252494220 - Service Update
Reduced Brake Performance

Models: 2025 Cadillac XT4
2025 Chevrolet Corvette
2025 Chevrolet Equinox
2025 GMC Terrain

General Motors is releasing Service Update N252494220 today.

What Should Dealers Do: Dealers should review IVH or the Dealer Maxis reports for open VINs in their inventory. Dealers can view the attached bulletin and it will also be displayed in Service Information tomorrow.

A Stock VIN list is not included as our records show there are no vehicles in dealer new inventory.

The Inventory tab of the Open Vehicle Report will contain Service Update Bulletin VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will not contain Service Update Bulletin VIN data because the intent of a Service Update Bulletin is to not inconvenience a customer with a special trip for service. Service Update Bulletins are to be completed when the customer is in for a regularly scheduled visit.

END OF MESSAGE

Service Update

N252494220 Reduced Brake Performance



Release Date: June 2025

Revision: 00

Attention: This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

Investigate Vehicle History (IVH) in the GM Global Warranty Management system MUST always be checked to confirm vehicle involvement and MUST be in OPEN status prior to beginning any required inspections and/or repairs. DO NOT use Service Information with VIN search, as it will not verify the VIN eligibility for field actions.

Make	Model	Model Year	
		From	To
Cadillac	XT4	2025	2025
Chevrolet	Corvette	2025	2025
Chevrolet	Equinox	2025	2025
GMC	Terrain	2025	2025

Investigate Vehicle History (IVH) in the GM Global Warranty Management system MUST always be checked to confirm vehicle involvement and MUST be in OPEN status prior to beginning any required inspections and/or repairs. DO NOT use Service Information with VIN search, as it will not verify the VIN eligibility for field actions.

Condition	Certain vehicles listed above may have a condition in which braking performance is reduced, vehicle top speed is limited, and MIL notification is provided to the customer.
Correction	Dealers are to replace the brake master cylinder assembly.

Parts

Quantity	Part Name	Part No.
1	VALVE KIT, ELEK TRACT CONT BRK PRESS MOD (Corvette W/ RPO JL9 or J55)	85695661
1	VALVE KIT, ELEK TRACT CONT BRK PRESS MOD (Corvette W/ RPO J58)	85695662
1	RESERVOIR KIT, BRK M/CYL (Corvette)	85165043
1	BRACKET, BRK M/CYL (Corvette)	86539201
1	RETAINER, BRK PED PUSH ROD (Corvette)	84364629
1	VALVE KIT, ELEK TRACT CONT BRK PRESS MOD (Equinox/Terrain)	26569958
1	RESERVOIR KIT, BRK M/CYL (Equinox/Terrain)	84857010
1	RETAINER, BRK PED (Equinox/Terrain)	26539133
1	VALVE KIT, ELEK TRACT CONT BRK PRESS MOD (XT4)	42907124
1	RESERVOIR KIT, BRK M/CYL (XT4)	84894475
1	RETAINER, BRK PED PUSH ROD (XT4)	84567897
As Req'd (Up to 1 pt)	FLUID-BRAKE (DOT 4) (US)	19299570
As Req'd (Up to 0.5 L)	FLUID-BRAKE (DOT 4) (CAN)	19299571

Reminder: Parts may be removed from SPRINT and Retail Inventory Management (RIM) and be non-returnable. Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect. There are a small number of vehicles anticipated that will need this fix. **Due to the limited initial parts availability, dealers are encouraged not to order these parts for use as shelf stock.**

Parts required to complete this recall are to be obtained from General Motors Customer Care and Aftersales (GMCCA). Parts are currently in limited supply. Order parts on a CSO = Customer Special Order only. DRO's may be cancelled. If a SPAC case is required, dealers should place a CSO order (not CSO3) and upgrade the order to a SPAC case themselves. Parts may have quantity limiters in effect. **All orders will be reviewed prior to being filled.**

Service Update

N252494220 Reduced Brake Performance



Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9107928	Brake Master Cylinder Replacement - With Power Brake Booster and Electronic Brake Control Module			
	Equinox/Terrain	2.8	ZFAT	N/A
	Corvette (Equipped with RPO J55)	4.2		
	Corvette (Equipped with RPO JL9, J56, or J57)	3.2		
XT4	3.2			

Note: The above labor time(s) are published direct from the Labor Time Guide.

Service Procedure

Replace the Brake Master Cylinder Assembly. Refer to *Brake Master Cylinder Replacement - With Power Brake Booster and Electronic Brake Control Module* in SI.

Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Pre-Owned (CPO), courtesy transportation vehicles, dealer shuttle vehicles, CarBravo, etc. in dealers' possession and subject to this field action must be held and inspected/repaired per the service procedure of this bulletin before customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Pre-Owned (CPO) vehicles currently in the dealers' inventory within the SHIFT Digital system will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the SHIFT Digital system, or once again be used in the Courtesy Transportation Program.

Dealer Reports – For USA & Export

The Inventory tab of the Open Vehicle Report will contain Service Update Bulletin VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will not contain Service Update Bulletin VIN data because the intent of a Service Update Bulletin is to not inconvenience a customer with a special trip for service. Service Update Bulletins are to be completed when the customer is in for a regularly scheduled visit.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



**We Support
Voluntary Technician
Certification**