

SS 287 Noise Emitter Connector

Applicable Vehicles

MT50e

Symptoms

Red Motor Warning, J1939 Faults, Watchdog Faults

Issue

Weather seal missing from chassis harness connection point to the noise emitter.

Solution

Inspect noise emitter to chassis harness connection for orange weather seal and corrosion. If corrosion is present replace all terminals with corrosion and replace orange weather seal inside of connector.

Labels :

Step Vans

Add tags



0 Kudos

Comment

