



## Silverware Drawer Magnets

|                       |                                                                                                                      |                          |             |
|-----------------------|----------------------------------------------------------------------------------------------------------------------|--------------------------|-------------|
| <b>Bulletin Type:</b> | TSB                                                                                                                  | <b>Publication Date:</b> | June 2025   |
| <b>Bulletin #(s):</b> | 25-013                                                                                                               | <b>Make(s):</b>          | Jayco       |
| <b>Job Code(s):</b>   | 9801635                                                                                                              | <b>Model(s):</b>         | Pinnacle FW |
| <b>Flat Rate(s):</b>  | 9801635A 0.10 HR Silverware Tray Magnet Inspection<br>9801635B .50 HR – Silverware Tray Magnet Inspection and Repair | <b>Model Year(s):</b>    | 2026        |

|                                    |                                                                      |
|------------------------------------|----------------------------------------------------------------------|
| <b>Incident:</b>                   | Silverware tray magnet installed with ½" magnet instead of ¾" magnet |
| <b>Affected Units:</b>             | 2026 Jayco Pinnacle FW                                               |
| <b>Parts Kit:25-013JT</b>          | Parts Kit #: 25-013JT<br>4 EA - CATCH,MAG BRSS STK PL .75 90DEG BEND |
| <b>Misc. Tools &amp; Supplies:</b> | #2 square bit and screw gun                                          |
| <b>Parts Return Information:</b>   | N/A                                                                  |


## SILVERWARE DRAWER MAGNETS INSPECTION

1. If the ¾" magnet on the left is installed, nothing more is needed. If the ½" magnet on the right is installed, proceed to change out with the ¾" magnet shown on the left.



## SILVERWARE DRAWER MAGNETS REPAIR INSTRUCTIONS

1. Figure 1 shows the location of the drawer where the magnet needs replaced.



2. The arrow in figure 2 shows the placement of the screw that needs to be removed so the old magnet can be replaced with the new.
3. Repair is complete.



Jayco's sole obligation under our limited warranty is to repair or replace defective materials and/or workmanship deemed our responsibility as determined by Jayco in our sole discretion. Jayco reserves the right to use new and/or remanufactured parts or materials of similar quality to complete any work, and to make parts and/or design changes as appropriate without notice to anyone. Jayco designs and/or materials changes are done without obligation to incorporate such changes in previously manufactured product. Jayco makes every reasonable effort to ensure field remedies will not adversely affect performance and/or safety of the unit. This field remedy is not intended to extend to future performance of this RV, or any of its materials, components or parts beyond the standard warranty period. The RV owner's obligation to notify Jayco, or one of its independent, authorized dealers, of a claimed defect does not modify any obligation placed on the RV owner to contact Jayco directly when attempting to pursue remedies under state or federal law.

903 South Main Street • P.O. Box 460 • Middlebury, IN 46540