



Service Bulletin

Bulletin No.: PIP6069

Date: June, 2025

PRELIMINARY INFORMATION

Subject: 10L80 MHO MHS MQC DTC's P1787 P27EC P187E P18A1

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500	2024		ALL	ALL	MHS MQC	ALL
Chevrolet	Suburban	2024		ALL	ALL	MHS MQC	ALL
Chevrolet	Tahoe	2024		ALL	ALL	MHS MQC	ALL
GMC	Sierra 1500	2024		ALL	ALL	MHS MQC	ALL
GMC	Yukon	2024		ALL	ALL	MHS MQC	ALL
GMC	Yukon XL	2024		ALL	ALL	MHS MQC	ALL

Involved Region or Country	North America Asean Asia/Pacific China Europe E Europe International Fleet Sales Israel Mid-East South America
Condition	SES MIL with any or all DTCs P1787, P27EC, P187E, P18A1 present.
Cause	Internal valve body.

Correction

If you encounter any of the above DTC's do not replace the TCM. Replace the Control Valve Body due to an internal concern. This PI will be deleted or updated into a TSB after further research.

Version	1
Modified	06/11/2025 — Created.

