



# Service Bulletin

Bulletin No.: PIP6071

Date: June, 2025

## PRELIMINARY INFORMATION

**Subject: Potential Chuggle, Surge, Hesitation on Acceleration, Misfire, P0300, P2097, P2251, P223C**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2023-2025		All	All	1.5 LSD	All
GMC	Terrain	2023-2025		All	All	1.5 LSD	All

<b>Involved Region or Country</b>	North America
<b>Condition</b>	Customers may notice a surge, misfire, chuggle, hesitation at tip in acceleration or MIL with P0300, P2097, P2251 P223C stored.
<b>Cause</b>	Potential skewed position 1 oxygen sensor.

### Correction

Replace the position 1 oxygen sensor, perform any applicable learn, and retest. Inspect the catalytic converter while sensor is out of the bore for any potential degradation to the catalyst bed.

### Parts Information

Refer to GM EPC for parts information per specific VIN.

<b>Version</b>	1
<b>Modified</b>	06/13/2025 Created on.

