



# Service Bulletin

Bulletin No.: PIP6019B

Date: June, 2025

## PRELIMINARY INFORMATION

**Subject: MIL Overheat condition P0494**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2024 - 2026		All	All	1.5 LSD	All
GMC	Terrain	2024 - 2026		All	All	1.5 LSD	All

<b>Involved Region or Country</b>	North America
<b>Condition</b>	MIL Illuminated, possible overheating engine, inoperative cooling fan, inoperative A/C.
<b>Cause</b>	DTC P0494 potential internal cooling fan failure. Engineering is currently investigating. The PI will be updated or replaced with TSB once a determination has been made.

### Correction

Replace the cooling fan and re-evaluate the concern.

### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4032260	Engine Coolant Fan Replacement	See Labor Time Guide

<b>Version</b>	3
<b>Modified</b>	10/24/2024 - Created. 02/07/2025 - Updated model years. 06/18/2025 - Updated model years and removed breakpoint.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION**

Copyright 2025 General Motors. All Rights Reserved.