



Service Bulletin

Bulletin No.: PIT6402

Date: June, 2025

PRELIMINARY INFORMATION

Subject: Automatic Level Control Module (ALCM) Fails Programming

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade IQ	2024-2026		ALL	ALL	ALL	ALL
Cadillac	Escalade IQL	2026		ALL	ALL	ALL	ALL
Chevrolet	Silverado EV	2024-2026		ALL	ALL	ALL	ALL
GMC	Sierra EV	2024-2026		ALL	ALL	ALL	ALL

Involved Region or Country	North America
Additional Options (RPO)	F47
Condition	A technician may encounter an issue when attempting to program the K5 Automatic Level Control Module where the module might fail programming during a standalone or Vehicle Wide Programming event. There may not be any DTC's recorded.
Cause	SW anomaly within the K5 Automatic Level Control Module.

Correction

If you experience this concern, remove the Automatic Level Control Module fuse F15UA for 5 minutes and reinstall and then reattempt Vehicle wide programming.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
8080728*	Remove and Install Automatic Level Control Module Fuse F15UA	0.2 Hrs.
*This is a unique Labor Operation for Bulletin use only.		

Version	1
Modified	Created on 06/18/2025.

