



Service Bulletin

Bulletin No.: PIP6076

Date: June, 2025

PRELIMINARY INFORMATION

Subject: Transmission fluid life will not stay at 100%

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2024-2025		All	All	All	All

Involved Region or Country	North America
Condition	When performing transmission oil life reset, on the subsequent ignition or drive cycle(s) the percentage may drop much more quickly than expected, even to low values.
Cause	Currently under investigation with G.M. Engineering.

Correction

Engineering is currently investigating. In the meantime please advise customer they may continue to drive the vehicle

This PI will be updated or replaced with TSB once a determination has been made

Version	1
Modified	06/27/2025 Created on.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2025 General Motors. All Rights Reserved.