



# Service Bulletin

Bulletin No.: PIP6076

Date: June, 2025

## PRELIMINARY INFORMATION

**Subject: Transmission fluid life will not stay at 100%**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2024-2025		All	All	All	All

<b>Involved Region or Country</b>	North America
<b>Condition</b>	When performing transmission oil life reset, on the subsequent ignition or drive cycle(s) the percentage may drop much more quickly than expected, even to low values.
<b>Cause</b>	Currently under investigation with G.M. Engineering.

### Correction

Engineering is currently investigating. In the meantime please advise customer they may continue to drive the vehicle

This PI will be updated or replaced with TSB once a determination has been made

<b>Version</b>	1
<b>Modified</b>	06/27/2025 Created on.

