



Anthem Hood Latch, Retrofit

Service Category Service Department

Section Function Group 821

Technician Skill Level B

Market North America

Applicability

Mack

Model Years	Models
2020-2022	AN

Introduction

Mack Trucks has determined that certain model year 2020 to 2022 Anthem trucks could experience excessive wear on the hood latch pins causing the hood to rattle during normal vehicle operation. Follow the instructions below to remove the hood release/cable assemblies and install rubber hood latch straps.

Production Change Information

This bulletin applies to vehicles built within the specified production changes below.

Brand	Engine	Emission Level	Starting Build Date	Ending Build Date
Mack	MP8	EM-USA17, EM-USA21	26-February-2019	22-November-2022

Warranty Information

NOTE: There will be no labor time coverage. Only parts will be covered.

Claim Type (used only when uploading from the Dealer Bus. Sys.)	B
Causal Part	82796225
SCC Authorization Code	S4548
Expiration Date	June 30, 2026



Parts Information

Part Numbers	Part Names	Quantity
23961452	Hood Latch Strap, Replacement kit	1

Required Tools & Equipment

N/A

Repair Procedure

1. Follow Technical Service Bulletin **M-821-028 Hood Latch Assembly, Retrofit** in Impact for installation instructions.