



# Service Bulletin

Bulletin No.: PIT6404

Date: June, 2025

## PRELIMINARY INFORMATION

**Subject: P0604 And/Or P0607 Set In The K56 Serial Data Gateway Module**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Envision	2024-2025		All	All	All	All
BrightDrop	Zevo 400	2024		All	All	All	All
BrightDrop	Zevo 600	2023-2024		All	All	All	All
Cadillac	CELESTIQ	2025		All	All	All	All
Cadillac	CT4	2023		All	All	All	All
Cadillac	CT5	2024-2025		All	All	All	All
Cadillac	CT6	2023-2024		All	All	All	All
Cadillac	Escalade	2025		All	All	All	All
Cadillac	Escalade ESV	2025		All	All	All	All
Cadillac	Escalade IQ	2025		All	All	All	All
Cadillac	LYRIQ	2024-2025		All	All	All	All
Cadillac	OPTIQ	2024-2025		All	All	All	All
Cadillac	XT4	2024-2025		All	All	All	All
Cadillac	XT5	2024-2025		All	All	All	All
Cadillac	VISTIQ	2024-2025		All	All	All	All
Chevrolet	BrightDrop 400	2025		All	All	All	All
Chevrolet	BrightDrop 600	2025		All	All	All	All
Chevrolet	Blazer EV	2025		All	All	All	All
Chevrolet	Colorado	2023-2025		All	All	All	All
Chevrolet	Corvette	2024		All	All	All	All
Chevrolet	Equinox	2025-2026		All	All	All	All
Chevrolet	Equinox EV	2024-2025		All	All	All	All
Chevrolet	Silverado EV	2024-2026		All	All	All	All
Chevrolet	Suburban	2025		All	All	All	All
Chevrolet	Tahoe	2025		All	All	All	All
GMC	Canyon	2023-2025		All	All	All	All
GMC	Hummer EV Pickup	2022		All	All	All	All
GMC	Sierra EV	2024-2026		All	All	All	All
GMC	Terrain	2025-2026		All	All	All	All

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
GMC	Yukon	2025		All	All	All	All
GMC	Yukon XL	2025		All	All	All	All

<b>Involved Region or Country</b>	North America
<b>Condition</b>	When performing diagnostics a technician may find DTC P0604 and/or P0607 set as a current or history in the K56 Serial Data Gateway Module with no other related symptoms.
<b>Cause</b>	Software anomaly in the Serial Data Gateway Module.

### Correction

The K56 Serial Data Gateway Module should NOT be replaced for these DTCs. Perform a global vehicle reset by disconnecting the 12 volt battery for 15 minutes and then clear the DTCs

**Note:** If you are working on an electric vehicle you MUST follow the procedure outlined in Service Information for 12 volt battery disconnection.

### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
* 5480958	Disconnect and Reconnect Battery Then Clear DTCs	0.3 Hrs.
*This is a unique Labor Operation for Bulletin use only.		

<b>Version</b>	1
<b>Modified</b>	06/30/25 Created on.

