



SIB 31 01 25

2025-06-27

SERVICE SOLUTION: Right Telescopic Fork Cover Allegedly Leaking

MODEL

Model	Model Description
K67	S 1000 RR
KM3	M 1000 R
KM9	M 1000 XR

SITUATION

On several M 1000 XR, M 1000 R and S 1000 RR vehicles with Front telescopic fork covers (Part numbers 31 42 1 754 557 and 31 42 1 757 701) lubricant residue is visible on the right fork cover.

This is assembly grease, not a leaking fork cover. Several covers have been leakage tested and no leak was found.

**PROCEDURE**

In the event of a complaint. Explain to the customer what the alleged leak is and proceed to clean the cover with a suitable cleaning agent.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

Supporting Materials

[picture_as_pdf SESO 31 01 25 Right Telescopic Fork Cover Allegedly Leaking.pdf](#)

