

Technical Service Bulletin (TSB)
Advanced Driver Assist System
Camera Module (ADCAM) Replacement

REFERENCE:	TSB: 08-201-25 GROUP: 08 - Electrical	Date:	June 26, 2025	REVISION:	—
VEHICLES AFFECTED:	2024 (KM) Jeep Wagoneer S This bulletin applies to vehicles built on or after September 01, 2024 (MDH 0901XX) and on or before May 19, 2025 (MDH 0519XX) equipped with Full Speed Fwd Collision Warn Plus (Sales Code LSU) and Adaptive Cruise Control w/Stop & Go (Sales Code NHZ).			MARKET APPLICABILITY: <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH NOTE: This bulletin applies to the North America market.	
CUSTOMER SYMPTOM:	Customers must comment on the following: <ul style="list-style-type: none"> "Adaptive Cruise Control/Active Drive Assist Unavailable/Service Required" popup in Instrument Panel Cluster (IPC). 				
CAUSE:	ADCAM was not flashed at plant				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 25-114, date of issue June 26, 2025. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves inspecting and possibly replacing the ADCAM.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
08-20-08-95	Advanced Driver Assist System Camera Module - Replace (0 - Introduction)	6 - Electrical and Body Systems	0.6 Hrs.
Failure Code	ZY	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1	68657799AN	Module, Camera Processor	

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Replace the Advanced Driver Assist System Camera Module. Refer to the detailed procedures available in DealerCONNECT > Service Library> under: 08 - Electrical / 8B - Driver Assistance / Assistance System Components / Modules / Removal and Installation.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.