

<b>Reference</b>	SSM76301
<b>Models</b>	Discovery Sport / L550 New Range Rover Evoque / L551
<b>Title</b>	Front Stabilizer Bar Link - Noisy
<b>Category</b>	Chassis
<b>Last modified</b>	11-Jun-2025 00:00:00
<b>Symptom</b>	304000 Suspension System

**Content****Model / Model Year / Derivative:**

Discovery Sport / 15MY onwards / All  
Range Rover Evoque / 19MY onwards / All

**Situation:**

JLR Engineering investigations have identified reports where the front stabilizer bar link(s) have been replaced by a retailer where a customer has reported a 'knocking' type noise from the front suspension. Following analysis of the returned old components the root cause of the issue cannot be determined.

**Action:**

Refer to the service request below.

**Service Request:**

To assist Engineering in identifying the root cause of specific noises, follow these steps:

## 1. Conduct a safe road test:

- Drive the vehicle over a road surface and conditions reported by the customer when the noise occurs.
- During the test, record any 'rattling' or 'knocking' noises from the front stabilizer bar link.

