

Reference	SSM76349
Models	New Range Rover / L460 New Range Rover Sport / L461
Title	Exterior Door Mirror Folding Beyond Intended Position
Category	Body
Last modified	24-Jun-2025 00:00:00
Symptom	103000 Mirrors

Content**Model / Model Year / Derivative**

Range Rover / 23MY Onwards / All
Range Rover Sport / 23MY Onwards / All

Situation:

JLR Engineering investigations have identified reports of the exterior door mirror folding beyond its intended position leading to a clash condition.

Action:

Refer to the service information below.

Service Information:

1. Confirm the customer symptom and inspect the exterior door mirror assembly for impact damage,

If damage is found, this repair **is not** covered by JLR's warranty policy and procedures, (see within the Warranty Manual > Warranty Terms and Conditions > B.1.7 - What is not covered by the Vehicle Warranties)

If no damage is found, replace the exterior door mirror assembly, in accordance with JLR's warranty policy and procedures.

(Ref 000397414 / 5538)

anBhdHRkcnM7MjAyNS0wNi0yNFQxNTozODozNS4zNDdaOzE2NS4yMjUuMzguMjQ0w==