



# Service Information

Offboard Diagnostic Information System Service (ODIS Service)

Number: VOS-25-47

Subject: Hotfix for 2025 ID BUZZ Recall 90A2 SVM code  
S4210AUTOBU54

Date: June 20, 2025

**Important:**

**We recommend installation of this hotfix on one diagnostic device ONLY. Hotfix must be removed immediately after performing the procedure.**

## 1.0 – Introduction

The hotfix is for the 2025 ID BUZZ Recall 90A2 SVM code S4210AUTOBU54. DTC ERP8118: No identification data could be determined for the following control modules:


0631 Multi-function steering wheel control module.

**!! The Hotfix must be removed after performing the diagnostic procedure. !!**

## 2.0 – Prerequisite

ODIS Service **latest Diagnostic Content version** must be installed.

To confirm the installed diagnostic content version in ODIS Service, go to:


Info >  Versions>Diagnostic data; didb\_GFS-v.en\_US: xxxxxxxx **X.XX.XX**




# Service Information

## 3.0 – Download Hotfix

1. Open a **Web Browser** on the diagnostic device and logon to **vwhub.com**
2. Navigate to **Elsa2Go>Service References>Software/Hardware Updates**
3. Search for **Hotfix for 2025 ID BUZZ Recall 90A2 SVM code S4210AUTOBU54 Zip File**
4. Click the **Hotfix for 2025 ID BUZZ Recall 90A2 SVM code S4210AUTOBU54 Zip File** and **save** it to your Windows desktop.
5. Close your browser.
6. Browse to the desktop and double-click the **Hotfix for 2025 ID BUZZ Recall 90A2 SVM code S4210AUTOBU54 Zip File** to open it.
7. Right click the file (example only) name and select **Copy**:



8. Right click anywhere on the Windows desktop and select **Paste**. This file icon (example) must appear on the desktop:






# Service Information


(continued)

## 4.0 – Install Hotfix into ODIS Service

1. Open ODIS Service (“Run as Administrator”)
2. Expand the **Data** submenu and click **Download** (under **Hotfix**):



3. Click **Continue**:




(continued)




# Service Information

- The Directory selection window will appear. Browse to and **highlight the Hotfix file** (*example only*), then click **Select Folder**:



- Click **OK**:



- Perform the diagnostic procedure.

## **Important:**

**The Hotfix must be removed after performing the procedure. Failure to do so will cause other vehicle diagnostics sessions to malfunction.**


(continued)




# Service Information

## 5.0 – Uninstall the Hotfix from ODIS Service

1. Select **Erase** (under Hotfix), then **Continue**:



2. Click **OK** and close ODIS Service:



**Please contact Diagnostic Tester Software Support by phone at 888-896-1298 or email [softwaresupport@vw.com](mailto:softwaresupport@vw.com) with any questions or concerns.**